APPENDIX A Pedestrian Report Card Assessment

Adams Street at Furnace Brook Parkway in Quincy Route 27 at West Street in Medfield





Central Transportation Planning Staff (CTPS) to the Boston Region MPO: www.ctps.org | 857.702.3700 | ctps@ctps.org

Ryan Hicks, Congestion Management Process Manager: www.ctps.org/cmp | 857.702.3661 | rhicks@ctps.org

Casey Claude, Bicycle and Pedestrian Program Manager: www.ctps.org/bicycle-pedestrian-activities | 857.702.3707 | cclaude@ctps.org

Pedestrian Report Card Assessment (PRCA):

Signalized Intersection

Intersection Location

Furnace Brook Parkway at Adams Street and Common Street, Quincy

Grading Categories	Score	Rating
Safety	1.2	Poor
System Preservation	2.0	Fair
Capacity Management and Mobility	1.7	Poor
Economic Vitality	3.0	Good

Transportation Equity		
High Priority Area		
Moderate Priority Area	٧	
Low Priority Area		

Category Ratings

Poor: Score 1.7 to 0

Transportation Equity Priority

Good: Score 2.3 to 3.0 High: Four (4) or Five (5) Factors Fair: 2.3 > Score > 1.7 Moderate: Two (2) or Three (3) Factors Low: Zero (0) or One (1) Factor

Grading Categories: Scoring Breakdown Signalized Intersection

Capacity Management and Mobility			
Performance Measure	Percentage	Score (out of 3.0)	Rating
Pedestrian Delay	43%	1.0	Poor
Sidewalk Presence	29%	2.0	Fair
Curb Ramp Presence	14%	2.0	Fair
Crosswalk Presence	14%	2.0	Fair
Total (Pedestrian Delay Score * 0.43) + (Sidewalk Presence Score * 0.29) + (Curb Ramp Presence Score * 0.14) + (Crosswalk Presence Score * 0.14)	100%	1.7	Poor

Economic Vitality				
Performance Measure Percentage Score (out of 3.0) Rating				
Pedestrian Volumes	100%	3.0	Good	

Meaning of Ratings Good: 3.0

Fair: 2.0 Poor: 1.0 **Transportation Equity Priority**

High: Four (4) or Five (5) Factors Moderate: Two (2) or Three (3) Factors Low: Zero (0) or One (1) Factor

Safety			
Performance Measure	Percentage	Score (out of 3.0)	Rating
Sufficient Crossing Time (Index)	38%	1.0	Poor
Pedestrian Crashes	38%	1.0	Poor
Pedestrian Signal Phase	13%	2.0	Fair
Vehicle Travel Speed	13%	1.0	Poor
Total (Sufficient Crossing Time (Index) Score * 0.38) + (Pedestrian Crashes Score * 0.38) + (Pedestrian Signal Presence Score * 0.13) + (Vehicle Travel Speed Score * 0.13)	100%	1.2	Poor

System Preservation				
Performance Measure Percentage Score (out of 3.0) Rating				
Sidewalk Condition	100%	2.0	Fair	

Transportation Equity Priority		
Area Condition	Yes/No	
Low Income Population =/> 32.32%	No	
Minority Population =/> 28.19%	No	
6.69%+ of Population > 75 Years of Age	Yes	
16.15%+ of Households w/o Vehicle	No	
Within ¼ Mile of School/College	Yes	





Central Transportation Planning Staff (CTPS) to the Boston Region MPO: www.ctps.org | 857.702.3700 | ctps@ctps.org

Ryan Hicks, Congestion Management Process Manager: www.ctps.org/cmp | 857.702.3661 | rhicks@ctps.org

Casey Claude, Bicycle and Pedestrian Program Manager: www.ctps.org/bicycle-pedestrian-activities | 857.702.3707 | cclaude@ctps.org

Pedestrian Report Card Assessment (PRCA):

Signalized Intersection

Intersection Location

Route 27 at West Street, Medfield

Grading Categories	Score	Rating	
Safety	1.3	Poor	
System Preservation	0	Poor	
Capacity Management and Mobility	0	Poor	
Economic Vitality	1.0	Poor	

Transportation Equity		
High Priority Area		
Moderate Priority Area	٧	
Low Priority Area		

Category Ratings

Poor: Score 1.7 to 0

Transportation Equity Priority

Good: Score 2.3 to 3.0 High: Four (4) or Five (5) Factors Fair: 2.3 > Score > 1.7 Moderate: Two (2) or Three (3) Factors Low: Zero (0) or One (1) Factor

Grading Categories: Scoring Breakdown Signalized Intersection

Capacity Management and Mobility					
Performance Measure Percentage Score (out of 3.0) Rating					
Pedestrian Delay	43%	0	Poor		
Sidewalk Presence	29%	0	Poor		
Curb Ramp Presence	14%	0	Poor		
Crosswalk Presence 14% 0 Poor					
Total (Pedestrian Delay Score * 0.43) + (Sidewalk Presence Score * 0.29) + (Curb Ramp Presence Score * 0.14) + (Crosswalk Presence Score * 0.14)	100%	0	Poor		

Economic Vitality				
Performance Measure Percentage Score (out of 3.0) Rating				
Pedestrian Volumes	100%	1	Poor	

Meaning of Ratings Good: 3.0

Fair: 2.0 **Poor**: 1.0

Transportation Equity Priority

High: Four (4) or Five (5) Factors Moderate: Two (2) or Three (3) Factors Low: Zero (0) or One (1) Factor

Safety			
Performance Measure	Percentage	Score (out of 3.0)	Rating
Sufficient Crossing Time (Index)	38%	3	Poor
Pedestrian Crashes	38%	0	Poor
Pedestrian Signal Phase	13%	0	Poor
Vehicle Travel Speed	13%	1	Poor
Total (Sufficient Crossing Time (Index) Score * 0.38) + (Pedestrian Crashes Score * 0.38) + (Pedestrian Signal Presence Score * 0.13) + (Vehicle Travel Speed Score * 0.13)	100%	1.3	Poor

System Preservation				
Performance Measure	Percentage	Score (out of 3.0)	Rating	
Sidewalk Condition	100%	0	Poor	

Transportation Equity Priority		
Area Condition	Yes/No	
Low Income Population =/> 32.32%	No	
Minority Population =/> 28.19%	No	
6.69%+ of Population > 75 Years of Age	Yes	
16.15%+ of Households w/o Vehicle	No	
Within ¼ Mile of School/College	Yes	